


Product identifier:
TCI 501 H.D.

Process identifier:
**Spray and brush aluminum welding soot cleaner
concentrate non-etching, non-staining**

NET: 020 L

\$15 carboy deposit



View Product Application/SDS:

tetra-chem.com/sc/501

For industrial and institutional use only.

This company assumes no responsibility or liability for personal injury or material destruction through improper handling or use of this product.

Please call our technical support line at 1-888-658-5515 for solutions to your industry.

© 2016 Origin of Canada



TETRA-CHEM INDUSTRIES LTD.

271 INGERSOLL ST. S.
INGERSOLL, ONTARIO
CANADA N5C 3J7

TEL: (519) 485-4370
TOLL FREE: (888) 658-5515
FAX: (855) 762-4446
WEB SITE: www.tetra-chem.com
EMAIL: info@tetra-chem.com

To reorder:

orders@tetra-chem.com



WARNING

May be corrosive to metals. Causes skin irritation. Causes serious eye irritation.

Precautions:

Keep only in original container. Wash hands or contact materials e.g. gloves thoroughly after handling. Wear protective gloves, protective clothing, eye protection, and face protection. IF ON SKIN: Wash with plenty of water or 5% baking soda solution. IF IN EYES: Rinse cautiously with water for several minutes. Remove contact lenses if present and easy to do - continue rinsing. Specific treatment (use a neutralizing spray of 5% baking soda). If skin irritation occurs: Get medical advice/attention. If eye irritation persists get medical advice/attention. Take off contaminated clothing and wash it before reuse. Absorb spillage to prevent material damage. Store in a corrosion resistant HDPE container.

See Safety Data Sheet – Voir la fiche de données de sécurité.

ATTENTION

Peut être corrosif pour les métaux. Provoque une irritation de la peau. Provoque une grave irritation des yeux.

Conseils:

Conserver uniquement dans le récipient d'origine. Lavez-vous les mains ou les matériaux de contact, par exemple gants soigneusement après la manipulation. Porter des gants de protection, des vêtements de protection, un équipement de protection des yeux et du visage. EN CAS DE CONTACT AVEC LA PEAU: laver abondamment à l'eau ou avec une solution de bicarbonate de soude à 5%. EN CAS DE CONTACT AVEC LES YEUX: rincer avec précaution à l'eau pendant plusieurs minutes. Enlever les lentilles de contact si elles sont présentes et faciles à faire - continuer à rincer. Traitement spécifique (utilisez un spray neutralisant à 5% de bicarbonate de soude). En cas d'irritation cutanée: consulter un médecin. Si l'irritation oculaire persiste, consulter un médecin. Enlever les vêtements contaminés et les laver avant de les réutiliser. Absorber les déversements pour éviter les dommages matériels. Stocker dans un conteneur en PEHD résistant à la corrosion.