


Product identifier:
TCI 1201 H.D.

Process identifier:
**Ferrous metal hot aqueous immersion
degreaser, rust, scale, paint stripper
and corrosion inhibitor powder**

NET: 004 kg



Scan QR for Instructions/SDS:

tetra-chem.com/sc/1201

For industrial and institutional use only.

This company assumes no responsibility or liability for personal injury or material destruction through improper handling or use of this product.

Please call our technical support line at 1-888-658-5515 for solutions to your industry.

© 2016 Origin of Canada



TETRA-CHEM INDUSTRIES LTD.

271 INGERSOLL ST. S.
INGERSOLL, ONTARIO
CANADA N5C 3J7

TEL: (519) 485-4370
TOLL FREE: (888) 658-5515
FAX: (855) 762-4446
WEB SITE: www.tetra-chem.com
EMAIL: info@tetra-chem.com

To reorder:

orders@tetra-chem.com



DANGER

May be corrosive to metals. Toxic if swallowed. Causes severe skin burns and eye damage. Causes serious eye damage. Harmful to aquatic life. Toxic to aquatic life with long-lasting effects.

Precautions:

Keep only in original container. Do not breathe dust. Wash skin thoroughly after handling. Do not eat, drink or smoke when using this product. Avoid release to the environment. Wear protective gloves, protective clothing, eye protection and face protection. IF SWALLOWED: Immediately call a hospital emergency department doctor. Rinse mouth. Do NOT induce vomiting. IF SWALLOWED: Rinse mouth. Do NOT induce vomiting. IF ON SKIN: Immediately apply a 5% vinegar solution. Wash with water. IF ON SKIN (or hair): Remove/Take off immediately all contaminated clothing. Rinse skin with water or mild vinegar solution and shower. IF INHALED: Remove person to fresh air and keep comfortable for breathing. IF IN EYES: Remove contact lenses if present and easy to do. Rinse cautiously with water or saline solution for several minutes - continue rinsing. Immediately call a hospital emergency department doctor. Specific treatment (Immediately apply a 5% vinegar solution) Then wash with water. Rinse mouth. Take off immediately all contaminated clothing and wash it before reuse. Wash contaminated clothing before reuse. Absorb spillage to prevent material damage. Collect spillage. Store locked up. Store in a corrosion resistant container of HDPE plastic. Dispose of contents in accordance with local, regional, national and international government regulations. Return container to supplier for recycling.

DANGER

Peut être corrosif pour les métaux. Toxique en cas d'ingestion. Provoque des brûlures de la peau et des lésions oculaires graves. Provoque des lésions oculaires graves. Nocif pour la vie aquatique. Toxique pour les organismes aquatiques, entraîne des effets néfastes à long terme.

Conseils:

Conserver uniquement dans le récipient d'origine. Ne pas respirer la poussière. Laver soigneusement la peau après manipulation. Ne pas manger, boire ou fumer en utilisant ce produit. Éviter le rejet dans l'environnement. Porter des gants de protection, des vêtements de protection, un équipement de protection des yeux et du visage. EN CAS D'INGESTION: Appeler immédiatement un médecin du service des urgences d'un hôpital. Rincer la bouche. NE PAS faire vomir. EN CAS D'INGESTION: Rincer la bouche. Ne PAS faire vomir. EN CAS DE CONTACT AVEC LA PEAU: Appliquez immédiatement une solution de vinaigre à 5%. Laver à l'eau. EN CAS DE CONTACT AVEC LA PEAU (ou les cheveux): Enlever / enlever immédiatement tout vêtement contaminé. Rincer la peau avec de l'eau ou une solution de vinaigre doux et prendre une douche. EN CAS D'INHALATION: Transporter la personne à l'air frais et garder son confort de respiration. EN CAS DE CONTACT AVEC LES YEUX: Enlevez les lentilles cornéennes si elles sont présentes et faciles à faire. Rincer avec précaution à l'eau ou avec une solution saline pendant plusieurs minutes. Continuer à rincer. Appelez immédiatement un médecin du service des urgences de l'hôpital. Traitement spécifique (Appliquer immédiatement une solution de vinaigre à 5%) Puis laver à l'eau. Rincer la bouche. Enlever immédiatement tous les vêtements contaminés et les laver avant de les réutiliser. Laver les vêtements contaminés avant de les réutiliser. Absorber les déversements pour éviter les dommages matériels. Recueillir le déversement. Magasin bloqué. Conserver dans un récipient en plastique PEHD résistant à la corrosion. Éliminer le contenu conformément aux réglementations gouvernementales locales, régionales, nationales et internationales. Retourner le conteneur au fournisseur pour recyclage.

See Safety Data Sheet — Voir la fiche de données de sécurité.