


Product identifier:  
**TCI 333 H.D.**

Process identifier:  
**Brushless non-etching welding soot  
cleaner from polished aluminum bulk  
tanker trailers (ready to use)**

NET: 020 L

\$15 carboy deposit



View Product Application/SDS:

[tetra-chem.com/sc/333](http://tetra-chem.com/sc/333)

*For industrial and institutional use only.*

This company assumes no responsibility or liability for personal injury or material destruction through improper handling or use of this product.

Please call our technical support line at 1-888-658-5515 for solutions to your industry.

© 2016 Origin of Canada



**TETRA-CHEM INDUSTRIES LTD.**

271 INGERSOLL ST. S.  
INGERSOLL, ONTARIO  
CANADA N5C 3J7

TEL: (519) 485-4370  
TOLL FREE: (888) 658-5515  
FAX: (855) 762-4446  
WEB SITE: [www.tetra-chem.com](http://www.tetra-chem.com)  
EMAIL: [info@tetra-chem.com](mailto:info@tetra-chem.com)

To reorder:

[orders@tetra-chem.com](mailto:orders@tetra-chem.com)



## WARNING

**May be corrosive to metal. Causes skin irritation. Causes serious eye irritation.**

Precautions:

Keep only in original container. Wash hands thoroughly after handling. Wear protective gloves and eye protection. IF ON SKIN: Wash with plenty of water or use a mild alkaline based rinse. IF IN EYES: Remove contact lenses if present and easy to do. Rinse cautiously with water or saline solution for several minutes. Specific treatment: Use mild alkaline solution to bring pH to 7 and use moisturizing eye drops for several days until eye ball feels perfectly normal again. If skin irritation occurs: Get medical attention. If eye irritation persists get medical attention. Take off contaminated clothing and wash it before reuse. Absorb spillage to prevent material damage. Store in a corrosion resistant container of HDPE.

See Safety Data Sheet – Voir la fiche de données de sécurité.

## ATTENTION

**Peut être corrosif pour le métal. Provoque une irritation de la peau. Provoque une grave irritation des yeux.**

Conseils:

Conservé uniquement dans le récipient d'origine. Se laver les mains soigneusement après manipulation. Porter des gants de protection et une protection oculaire. EN CAS DE CONTACT AVEC LA PEAU: Laver abondamment à l'eau ou utiliser un rince-bouche doux à base alcaline. EN CAS DE CONTACT AVEC LES YEUX: Enlevez les lentilles cornéennes si elles sont présentes et faciles à faire. Rincer avec précaution avec de l'eau ou une solution saline pendant plusieurs minutes. Traitement spécifique: Utilisez une solution alcaline douce pour amener le pH à 7 et utilisez des gouttes oculaires hydratantes pendant plusieurs jours jusqu'à ce que la boule redevienne parfaitement normale. En cas d'irritation cutanée: consulter un médecin. Si l'irritation oculaire persiste, consulter un médecin. Enlever les vêtements contaminés et les laver avant de les réutiliser. Absorber les déversements pour éviter les dommages matériels. Conserver dans un récipient en PEHD résistant à la corrosion.